


**Please be aware the only difference
between those 2 turbos
is in the actuator socket.**

RCT50014R
49335-00585

RCT50015R
49335-00644



They look identical otherwise.