



Please be aware
this turbocharger exists in 2 versions

775274

-5002S	-5003S
RCT30162R	RCT30324R
Temp sensor hole  A photograph of the RCT30162R turbocharger. A blue arrow points from the text 'Temp sensor hole' to a small circular hole on the left side of the compressor housing.	No hole  A photograph of the RCT30324R turbocharger. A blue arrow points from the text 'No hole' to the same location on the left side of the compressor housing, where there is no hole.

recoturbo