recoturbo


Please save the bypass valve on following turbochargers:

RCT30214R - 821943

RCT30230R - 821942

RCT30264R - 825759

RCT30265R - 825758









Spares are not available at the moment.

Installing a turbocharger without it will cause boost issues.